COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY UTILITIES COMPANY) CASE NO. 91-26	9
ALLEGED FAILURE TO COMPLY WITH) }	
COMMISSION REGULATION 807 KAR 5:006, SECTION 24		

ORDER TO SHOW CAUSE

Kentucky Utilities Company ("KU"), which engages in the distribution of electricity to the public for compensation, for light, heat, power, and other uses, is a utility under the Commission's jurisdiction.

KRS 278.280(2) directs the Commission to prescribe rules and regulations for the performance of services by utilities. Pursuant to this statutory directive, the Commission promulgated Commission Regulation 807 KAR 5:006, Section 24, which requires a utility to submit to the Commission a summary written report of any utility-related accident which results in death or serious injury. This report must be submitted within 7 days of the accident.

Commission Staff has submitted to the Commission an Electrical Utility Accident Investigation Report dated July 8, 1991 which alleges:

1. On June 10, 1991, Wayne Prewitt was seriously injured in Lexington, Kentucky, while working on KU facilities.

- 2. KU submitted a summary written report of this accident to the Commission on June 27, 1991.
- 3. KU violated Commission Regulation 807 KAR 5:006, Section 24, by failing to submit a summary written report of this accident within 7 days of the accident's occurrence.

The Commission, on its own motion, HEREBY ORDERS that:

- 1. KU shall submit to the Commission within 20 days of the date of this Order a written response to the allegations contained in the Electrical Utility Accident Investigation Report which is attached hereto and incorporated herein as Appendix A.
- 2. KU shall appear on October 8, 1991, at 1:00 p.m., Eastern Daylight Time, in Hearing Room 1 of the Commission's offices at 730 Schenkel Lane, Frankfort, Kentucky, for the purposes of presenting evidence concerning the incident which is the subject of the Electrical Utility Accident Investigation Report, specifically the alleged violations of Commission Regulation 807 KAR 5:006, Section 24, and of showing cause, if any it can, why it should not be subjected to the penalties of KRS 278.990 for its alleged failure to comply with Commission Regulations.

Done at Frankfort, Kentucky, this 9th day of August, 1991.

PUBLIC SERVICE CONNISSION

Commissioner

ATTEST:

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 91-269 DATED 8/09/91

ELECTRIC UTILITY ACCIDENT INVESTIGATION

DATE OF THIS REPORT: July 8, 1991 SUBNITTED BY: Kyle Willard

NAME OF UTILITY: Kentucky Utilities Co.

ACCIDENT REPORTED BY: Jim Brackney

DATE & TIME ACCIDENT OCCURRED: June 10, 1991 8:50 A.M.

DATE & TIME UTILITY LEARNED OF ACCIDENT: June 10, 1991 9:00 A.M.

DATE & TIME ACCIDENT REPORTED: June 25, 1991 4:15 P.M.

DATE OF ACCIDENT INVESTIGATION: June 26, 1991

DATE SUMMARY WRITTEN REPORT WAS RECEIVED FROM UTILITY: June 27, 1991

PERSONS ASSISTING IN THE INVESTIGATION: Jim Brackney and Bill Dickey

of Kentucky Utilities Co.

VICTIM(S):

1. NAME: Wayne Prewitt SEX: M AGE: UKN

FATAL: NO NAME OF EMPLOYER: Shely Construction Co.

INJURIES: Flash burn to face and neck

2. NAME: SEX: AGE:

FATAL: NAME OF EMPLOYER:

INJURIES:

3. NAME: SEX: AGE:

FATAL: NAME OF EMPLOYER:

INJURIES:

ELECTRICAL UTILITY ACCIDENT INVESTIGATION (Continued)

- LOCATION OF ACCIDENT SITE: Newtown Circle, Lexington, KY
- Foreman, William Blanton Groundman, and Wayne Prewitt Lineman (operating from truck bucket with full safety attire) had installed a mechanical jumper to remove a cutout and lightning arrester. (See Attachment A) Mr. Prewitt attempted to disconnect the hot lead from the bottom of the cutout, having to jerk the lead loose. In so doing he inadvertently made contact with the arrester, creating a flash, resulting in burns to his face and neck.
- SOURCE OF INFORMATION: Robert Nipper of Shely Construction Co., Alan

 Lewis of Kentucky Utilities Co., Kentucky Utilities Company

 Summary Written Report, and an on-site investigation.
- PROBABLE VIOLATIONS OF COMMISSION REGULATIONS: The Summary Written

 Report was received 17 days after the accident transpired.

 Therefore Kentucky Utilities Co. is in probable violation of 807

 KAR 5:006, Section 24; which requires that a Summary Written

 Report be filed within seven (7) days.
- RECOMMENDATIONS: Due to Kentucky Utilities Company's probable violation of 807 KAR 5:006, Section 24, it is recommended that the Commission consider action in accordance with KRS 278.990. In addition, the Utility did not notify the Commission until 15 days

enough to allow for a meaningful investigation by Commission staff, therefore, it is further recommended that Kentucky Utilities Co. take action to correct this notification problem on any future incident.

CORRECTIVE ACTION: Corrective action has been recommended.

LINE CLEARANCES

		As Measured	Minimum Allowed by NESC
A.	AT POINT OF ACCIDENT	A: 34'-4"	
	Phase conductor to ground elevation:	B: 34'-4" C: 34'-4"	18'-6"
	Neutral conductor to ground elevation:	27'-3"	15'-6"
	Secondary phase conductor to ground elevation:	26'-3"	16'-6"
	TV cable to ground elevation:	22'-1"	15'-6"
	Communication conductor to ground elevation:	20'-9"	15'-6"
B.	AT LOWEST POINT OF SPAN	A: 37'-3"	
	Phase conductor to ground elevation:	B: 37'-3" C: 37'-3"	18'-6"
	Neutral conductor to ground elevation:	31'-3"	15'-6"
	Secondary phase conductor to ground elevation:	29'-7"	16'-6"
	TV cable to ground elevation:	25'-4"	15'-6"
	Communication conductor to ground elevation:	22'-10"	15'-6"
	Span guy wire to ground elevation:	20'-0"	15'-6"
			

C. SPAN LENGTH 147'-8"

Date the line or facilities were constructed: June 1991

Utility: Kentucky Utilities Co.

Date: June 26, 1991

Time: 2:30 P.M.

Approximate temperature: 80 DEGREES F

Measurements made by: Al Lewis of Kentucky Utiligies/Co.

Submitted by:

Kyle Willard, Engineer Communications and Electric Branch

KENTUCKY UTILITIES COMPANY

ONE QUALITY STREET
LEXINGTON, KENTUCKY
40507
TELEPHONE 808-255-2100

June 25, 1991

ANTONIA THE WARES

Mr. John Land
Public Service Commission
730 Schenkel Lane
P.O. Box 615
Frankfort, KY 40602

Dear John:

SUBJECT: FLASH & BURN ACCIDENT

WAYNE PREWITT DOA: 6/10/91

We are enclosing a copy of our Report of Accident - Public where an employee of Shely Construction Company received Flash burns to face and neck.

If you have any questions please advise.

Thank you.

Sincerely,

James A. Brackney, P.E. Director, Insurance & Claims

JAB/ss Enclosure

`	DEDORT OF ACCOUNTY PARTY	Kentucky		
P 100 Chairn No	Personal Injury or property demage INJECTOR THE TOTAL CHILTY	JN 3 99 Lexington, E	13 to 20	
TIME AND PLACE OF ACCIDENT	i	1 Time 8:50 PM Lordon Newtown Lexington come Payette		
RMT 6-14-91 REASON INJURED	Name			
PUBLIC PROPERTY DAMAGED	Climer's Name Address Description of Property Damaged			
ACCIDENT	from bucket truck) had install cutout and arrester. After in out of the bottom of the cutou to jerk the wire. When the wi	ert Nipper - Foreman, Wayne Pre lliam Blanton - Groundman (Wayn ed a mechanical jumper to clear stalling the jumper, Wayne was	witt - Lineman. e was operating up and remove a taking the hot lead ing this and had into the bottom	
WITNESS OR PERSONS PRESENT	Name 1. Robert Nipper 2. Glen Ferrell 3. William Blanton	Address	Phone	
m g FM	Report Made By QUAN Revisa Report Approved By 77 35 Custo (Dies.	•	Dess 6-11-91	

P. S. C. ATTACHMENT B ACCIDENT AND TROUBLE REPORT FORM

TODAY'S DATE	4/25/5/	TIME	4:15	·
COMPANY Kentuky	utilities			_
PERSON REPORTING INCIDENT: NAME:	Jena B	rukna		
TITLE:				_
ADDRESS:	!			_
PHONE NO:	606/	288-1	1/38	_
	× × × /			=
ACCIDENT DESCRIPTION:	bun to	fue	T nech	
			·	-
VICTIMS NAMES: Wayne Preme	SEX_M AGE_	DEATH_	INJURY	_
	SEX AGE_			
	SEXAGE_	DEATH	INJURY	_
LOCATION OF ACCIDENT:	·····	<u></u>		
TIME OF OCCURRENCE:				
	* <u>*</u>	-		_
TROUBLE DESCRIPTION:		<u></u>		 ,
			, - :	
TIME OF OCCURRENCE: Time 10,	191/			
TIME OF RESUMPTION OF NORMAL SER	RVICE:			
NUMBER OF CUSTOMERS AFFECTED:				/
	SIGNED	en Pour	w /;	lake h
	DATE	4/17	19/	nucle,

Public	SERVICE COMMISSION	OF	KY.
	EMEINEENING DIVISION		
	Frankfort, Ky.		

Calculation Sheet

Date	No
Made by	
Charles be	

Temporary Cutout (inc. SA fuzz) Transformer	Utility		Checked by		
(Jumper)		Primary	Lightning Arrector		
Transformer		3ypa			
		· · · · · · · · · · · · · · · · · · ·	Transformer		
	,				

In order to replace the cutout, a temporary By Pars line between the Lightning Herosfer and the Transformer are established.

Accident occurred when into ut was partially removed from highwing arrestor node and ground lie inadvertually connected with Arrestor causing phase to grown short with resulting flash.

